



<p style="text-align: center;"> SPRINGS WINDOW FASHIONS <small>the Best Experience Company</small>  </p> <p style="text-align: center;"> Springs Window Fashions Customer Service </p>	<p style="text-align: center;">Title:</p>	<p style="text-align: center;">Use If/When:</p>
	<p style="text-align: center;">Light Gap Between Slats- 2" or greater</p>	<p style="text-align: center;">Light Gap Between Slats</p>
<p style="text-align: center;">Last Revised: 02/21/08</p>		

1. Using a carpenters level, make sure the headrail is level from side to side and front to back. If necessary, adjust brackets and reinstall blind.



2. If the top slat is hitting the headrail, **gently** pull down on the tops of the ladder tapes to see if the top slat will move down, allowing full closure.



3. Longer and wider than average blinds, no holes blinds, or blinds with decorative tapes may have a gap of 1/4-1/2" between the slats of the blind. This is the nature of the product and can not be corrected. The longer the blind, the larger the gaps will be toward the bottom.

